

1/21

FIG. 1 (a)






FIG. 1 (b)




2/21

FIG.2




16




4/21

FIG.4



5/21

FIG. 5



6/21

FIG. 6 (b)

DIRECTLY BELOW ANKLE GROUND CONTACT SENSOR : OFF  
DIRECTLY BELOW MP GROUND CONTACT SENSOR : ON





FIG. 6 (a)


DIRECTLY BELOW ANKLE GROUND CONTACT SENSOR : ON  
DIRECTLY BELOW MP GROUND CONTACT SENSOR : OFF



7/21

FIG. 7 (a)


DIRECTLY BELOW ANKLE  
GROUND CONTACT SENSOR : ON  
DIRECTLY BELOW MP  
GROUND CONTACT SENSOR : ON



FLOOR REACTION FORCE ACTING POINT

FIG. 7 (b)


DIRECTLY BELOW ANKLE  
GROUND CONTACT SENSOR : ON  
DIRECTLY BELOW MP  
GROUND CONTACT SENSOR : ON



FLOOR REACTION FORCE ACTING POINT

FIG. 7 (c)

DIRECTLY BELOW ANKLE  
GROUND CONTACT SENSOR : ON  
DIRECTLY BELOW MP  
GROUND CONTACT SENSOR : ON




FLOOR REACTION FORCE ACTING POINT






9/21




10/21




11/21

FIG.11

LEVEL-GROUND WALKING




12/21



13/21


FIG.13  
STAIRCASE DESCENT WALKING



14/21


FIG.14

STAIRCASE DESCENT WALKING




15/21

FIG.15  
STAIRCASE ASCENT WALKING



16/21

FIG.16







17/21

FIG.17

SITTING ONTO CHAIR




18/21




19/21

FIG.19



20/21

FIG. 20



21/21

FIG. 21

